IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number:

7,804,557

Issued:

September 28, 2010

Name of Patentee:

Schanz et al.

Title of Invention:

TRIGGER MECHANISM FOR FLUORESCENT TUBES

Commissioner for Patents

P.O. Box 1450 Alexandria, VA

ATTN: Certificate of Correction Branch

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 CFR 1.322(a))

1. Attached, in duplicate, is Form PTO-1050, with at least one copy being suitable for printing.

NOTE: Form PTO-1050, using the column and line number in the printed patent, should be used exclusively regardless of the length or complexity of the subject matter. MPEP S 1485.

NOTE: The patent grant should be retained by the patentee. The PTO does not attach the certificate of correction to the patentee's copy of the patent. The patent grant will be returned to the patentee if submitted, MPEP S 1485.

2. The exact page and line number where the errors are shown correctly in the application file are:

Column 4

Line 10, after "second current signal" insert -- and sets the value of the lamp current signal--

NOTE: This information should be identified in this request, however, on Form PTO-1050, only the column and line number in the printed patent should be used. MPEP S 1485.

I hereby certify that this correspondence (along with any paper referred to as being attached or enclosed) is being filed electronically via EFS-web with the Commissioner for Patents on the date indicated below

3. Please send the Certificate to:	
Name: <u>Patrick J. O'Shea, Esq.</u>	
Address: O'Shea Getz P.C.	
1500 Main Street, Suite 912	
Springfield, Massachusetts 01	<u>115</u>
,	Signature(s) of patentee(s)
Or Harman Becker Automotive Systems Gm (TYPE OR PRINT NAME OF ASSIGNEE)	bH Signature of assignee or person authorized to sign on behalf of assignee
[] Assignment recorded on:	
	Patrick O'Shea, Esq. (TYPE OR PRINT NAME OF AUTHORIZED PERSON SIGNING)
	Attorney of record Title of authorized person signing
[] Recordal of assignment attached	
[] Attached is a "CERTIFICATE UNDE to take action in this case.	CR 37 CFR 3.73(b)," establishing the right of the assignee
	ay be issued at the request of the patentee or [THE PATENTEES] ASSIGNEE." 37 CFR CAN BE SIGNED BY THE ATTORNEY OF RECORD WHO ACTS ON BEHALF

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

SERVIN 10/ VIE OF SOMMESTICK				
	Page _	1	of	1
PATENT NO. : 7,804,557	-		-	
APPLICATION NO.: 11/526,233				
ISSUE DATE : September 28, 2010				
INVENTOR(S) : Schanz et al.				
It is certified that an error appears or errors appear in the above-identified patent and the is hereby corrected as shown below:	at said	Lette	rs Pa	atent
Column 4 Line 10, after "second current signal" insert and sets the value of the lamp current signal				

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Patrick J. O'Shea, Esq., O'Shea Getz P.C. 1500 Main Street, Suite 912 Springfield, MA 01115

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.